Metric 6H GO And NO GO Screw Thread Plug Gauges



| Metric 6H GO And NO GO Screw Thread Plug Gauges | | | | | | | | | | | | | | |
|---|--------|----------|----------|---------------|--------|--------|------|----------|--------|------|------|--------|------------|------|
| Thread | M1.6 | M1.8 | M2 | M2.2 | M2.5 | M2.5 | M3 | M3 | M3.5 | M3.5 | M4 | M4 | M4 | M5 |
| Pitch | 0.35 | 0.35 | 0.4 | 0.45 | 0.35 | 0.45 | 0.35 | 0.5 | 0.35 | 0.6 | 0.35 | 0.5 | 0.7 | 0.5 |
| Left Hand | | | ٧ | | | ٧ | ٧ | ٧ | | ٧ | | ٧ | ٧ | |
| | | | | | | | | | | | | | | |
| Thread | M5 | M5 | M6 | M6 | M6 | M8 | M8 | M8 | M8 | M10 | M10 | M10 | M10 | M10 |
| Pitch | 0.75 | 0.8 | 0.5 | 0.75 | 1 | 0.5 | 0.75 | 1 | 1.25 | 0.5 | 0.75 | 1 | 1.25 | 1.5 |
| Left Hand | | ٧ | ٧ | ٧ | ٧ | | ٧ | ٧ | ٧ | | ٧ | ٧ | ٧ | ٧ |
| | | | | | | | | | | | | | | |
| Thrrad | M12 | M12 | M12 | M12 | M12 | M12 | M14 | M14 | M14 | M14 | M14 | M16 | M16 | M16 |
| Pitch | 0.5 | 0.75 | 1 | 1.25 | 1.5 | 1.75 | 0.5 | 0.75 | 1 | 1.25 | 1.5 | 0.5 | 1 | 1.25 |
| Left Hand | | | ٧ | ٧ | ٧ | ٧ | | | ٧ | ٧ | ٧ | | ٧ | ٧ |
| | | | | | | | | | | | | | | |
| Thread | M16 | M16 | M18 | M18 | M18 | M18 | M20 | M20 | M20 | M20 | M20 | M22 | M22 | M22 |
| Pitch | 1.5 | 2 | 1 | 1.25 | 1.5 | 2 | 1 | 1.25 | 1.5 | 2 | 2.5 | 1 | 1.25 | 1.5 |
| Left Hand | ٧ | ٧ | ٧ | | ٧ | ٧ | ٧ | | ٧ | ٧ | ٧ | ٧ | | ٧ |
| Thread | M22 | M22 | M24 | M24 | M24 | M24 | M25 | M25 | M25 | M27 | M27 | M27 | M27 | M28 |
| Pitch | 2 | 2.5 | 1 | 1.5 | 2 | 3 | 1 | 1.5 | 2 | 1 | 1.5 | 2 | 3 | 1 |
| Left Hand | ∠ √ | 2.5 √ | 1 | 1.5 V | ۷ ۷ | 3 √ | ٧ | 1.5 V | ∠ √ | 1 | 1.5 | ∠ √ | - 3 - √ | ٧ |
| Left Hallu | ٧ | ٧ | ٧ | ٧ | ٧ | V | ٧ | ٧ | ٧ | | | V | V | ٧ |
| Thread | M28 | M30 | M30 | M30 | M30 | M30 | M33 | M33 | M33 | M33 | M33 | M36 | M36 | M36 |
| Pitch | 1.5 | 1 | 1.5 | 2 | 3 | 3.5 | 1 | 1.5 | 2 | 3 | 3.5 | 1 | 1.5 | 2 |
| Left Hand | ٧ | ٧ | ٧ | <u>−</u> √ | ٧ | ٧ | | | | | ٧ | _ | | |
| | - | - | | - | - | - | | | | | - | | | |
| Thread | M36 | M36 | M39 | M39 | M39 | M42 | M42 | M42 | M42 | M42 | M45 | M45 | M45 | M45 |
| Pitch | 3 | 4 | 1.5 | 2 | 3 | 1 | 1.5 | 2 | 3 | 4.5 | 1.5 | 2 | 2 | 4.5 |
| Left Hand | - | ٧ | | | ٧ | | ٧ | - √ | ٧ | ٧ | | ٧ | | |
| | | | | | | | | | | | | | | |
| Thread | M48 | M48 | M48 | M48 | M52 | M56 | M60 | | | | | | | |
| Pitch | 1.5 | 2 | 3 | 5 | 2.5 | 5.5 | 5.5 | | | | | | | |
| Left Hand | | | | ٧ | | ٧ | | | | | | | | |

Screw Plug Gauges = 6H