## Metric 6g GO And NO GO Screw Thread Ring Gauges



				Metr	ic 6g GO	And NO	GO Screw	/ Thread	Ring Gau	ges				
Thread	M1.4	M1.6	M1.8	M2	M2.2	M2.5	M2.5	M3	M3	M3.5	M3.5	M4	M4	M4
Pitch	0.3	0.35	0.35	0.4	0.45	035	0.45	0.35	0.5	0.35	0.6	0.35	0.5	0.7
Left Hand				٧			٧	٧	٧		٧		٧	٧
Thread	M5	M5	M5	M6	M6	M6	M8	M8	M8	M8	M10	M10	M10	M10
Pitch	0.5	0.75	0.8	0.5	0.75	1	0.5	0.75	1	1.25	0.5	0.75	1	1.25
Left Hand			٧	٧	٧	٧		٧	٧	٧		٧	٧	٧
Thrrad	M10	M12	M12	M12	M12	M12	M14	M14	M14	M14	M14	M14	M16	M16
Pitch	1.5	0.5	0.75	1	1,25	1.5	0.5	0.75	1	1.25	1.5	2	0.5	0.75
Left Hand	٧		٧	٧	٧	٧			٧	٧	٧	٧		
Thread	M16	M16	M16	M16	M16	M18	M18	M18	M18	M18	M20	M20	M20	M20
Pitch	1	1.25	1.5	2	2.5	1	1.25	1.5	2	2.5	1	1.25	1.5	2
Left Hand	٧	٧	٧	٧		٧		٧	٧		٧		٧	٧
Thread	M20	M22	M22	M22	M22	M22	M24	M24	M24	M24	M25	M25	M25	M28
Pitch	2.5	1	1.25	1.5	2	2.5	1	1.5	2	3	1	1.5	2	1
Left Hand	٧	٧		٧	٧	٧	٧	٧	٧	٧	٧	٧	٧	
Thread	M28	M28	M30	M30	M30	M30	M30	M33	M33	M33	M33	M33	M36	M36
Pitch	1.25	1.5	1	1.5	2	3	3.5	1	1.5	2	3	3.5	1	1.5
Left Hand	٧	٧	٧	٧	٧	٧	٧					٧		
Thread	M36	M36	M36	M39	M39	M39	M39	M42	M42	M42	M42	M42	M45	M45
Pitch				1.5									1.5	
Left Hand	2	3	4 √	1.5	2	3 √	4 V	1	1.5 √	2 V	3 √	4.5 √	1.5	2 √
zert Hand			,			•	•		•	·	•	•		•
Thread	M45	M45	M48	M48	M48	M48	M48	M52						
Pitch	3	4.5	1.5	2	3	5	5	5						
Left Hand		٧				٧	٧							

Screw Ring Gauges - 6g