


## Torx Drive Shoulder Screws



Torx Drive Shoulder Screws						
<b>d1-Shoulder Dia</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>8</b>	<b>10</b>	<b>12</b>
<b>L1-(+0.25/-0.00)</b>	<b>4 - 10</b>	<b>10 - 30</b>	<b>10 - 50</b>	<b>12 - 50</b>	<b>16 - 70</b>	<b>16 - 70</b>
<b>d2-Thread</b>	<b>M3</b>	<b>M4</b>	<b>M5</b>	<b>M6</b>	<b>M8</b>	<b>M10</b>
<b>L2</b>	<b>4.8</b>	<b>8.5</b>	<b>9.5</b>	<b>11</b>	<b>13</b>	<b>16</b>
<b>d3</b>	<b>6</b>	<b>9</b>	<b>10</b>	<b>13</b>	<b>16</b>	<b>18</b>
<b>h</b>	<b>3</b>	<b>4</b>	<b>4.5</b>	<b>5.5</b>	<b>7</b>	<b>9</b>
<b>Drive</b>	<b>TX8</b>	<b>TX10</b>	<b>TX20</b>	<b>TX25</b>	<b>TX30</b>	<b>TX40</b>

Material: A2 Stainless Steel

INFORMATION AND DRAWINGS PROVIDED ARE FOR REFERENCE ONLY