

UNC And UNF 2B GO And NO GO Screw Thread Plug Gauges



UNC And UNF 2B GO And NO GO Screw Thread Plug Gauges														
Thread	#0	#1	#2	#3	#4	#5	#6	#8	#10	#12	1/4	5/16	3/8	7/16
UNC T.P.I		64	56	48	40	40	32	32	24	24	20	18	16	14
UNF T.P.I	80	72	64	56	48	44	40	36	32	28	28	24	24	20
Left Hand									√		√	√	√	√

Thread	1/2	9/16	5/8	3/4	7/8	1	1-1/8	1-1/4	1-3/8	1-1/2	1-3/4	2		
UNC T.P.I	13	12	11	10	9	8	7	7	6	6	5	4-1/2		
UNF T.P.I	20	18	18	16	14	12	12	12	12	12				
Left Hand	√	√	√	√	√	√								

Screw Plug Gauges = 2B

UKAS Certification Can Be Supplied On The Above, IF Required At Additional Cost