



## Molded In-Inserts



Through Hole Brass Molded In-Inserts							
Thread	M3	M3.5	M4	M5	M6	M8	M10
F-Across Flats	4.8	6.3	7.1	8.7	9.4	12.4	15.5
H-Diameter	4.4	6	6.7	8	9.1	12.1	15.2
A-Across Points	5.6	7.4	8.3	10.2	10	14.4	18.1
L-Length	3.7	5.9	5.9	8.3	9.6	10.8	12.7



Blind Hole Brass Moldd In-Inserts							
Thread	M3	M3.5	M4	M5	M6	M8	M10
F-Across Flats	4.8	6.3	7.1	8.7	9.4	12.4	15.5
H-Diameter	4.4	6	6.7	8.3	9.1	12.1	15.2
A-Across Points	5.6	7.4	8.3	10.2	10	14.4	18.1
L-Length	6.7	7.9	8.7	10.3	12.3	14.7	17

INFORMATION AND DRAWINGS PROVIDED ARE FOR REFERENCE ONLY